



SUMGAS Q2 PRESSURE TEMPERATURE CHART				
TEMP		R502	502A	
C	F	PSI	BUBBLE PSI	DEW PSI
-40	-40	4	7	3
-38	-36	6	9	4
-36	-33	8	11	6
-34	-29	10	13	8
-32	-26	12	15	9
-30	-22	14	17	11
-28	-18	17	19	13
-26	-15	19	22	16
-24	-11	22	24	18
-22	-8	25	27	20
-20	-4	28	30	23
-18	0	31	33	26
-16	3	34	36	28
-14	7	38	40	31
-12	10	42	43	35
-10	14	46	47	38
-8	18	50	51	42
-6	21	54	55	45
-4	25	59	60	49
-2	28	64	64	54
0	32	69	69	58
2	36	74	74	63
4	39	80	79	67
6	43	86	84	72
8	46	92	90	78
10	50	98	96	83
12	54	105	102	89
14	57	112	108	95
16	61	119	115	101
18	64	126	121	107
20	68	134	128	114
22	72	142	136	121
24	75	150	143	128
26	79	159	151	136
28	82	168	159	143
30	86	178	168	152
32	90	187	176	160
34	93	197	185	169
36	97	208	195	178
38	100	219	205	187
40	104	230	215	197
42	108	241	225	207
44	111	253	235	217
46	115	266	246	228
48	118	278	258	239
50	122	292	269	250
52	126	305	281	262
54	129	319	293	274
56	133	334	306	287